



Exmark Recalls Commercial Walk-Behind Mowers Due to Injury Hazard

Consumers should stop using this product unless otherwise instructed. It is illegal to resell or attempt to resell a recalled consumer product.

Recall date: December 10, 2013

Recall number: 14-045

Recall Summary

Name of product:

Commercial Walk-Behind Mowers

Hazard:

The mower's blade can break and injure the user and others nearby.

Remedy:

[Repair](#)

Consumer Contact:

Exmark at (800) 667-5296 from 8 a.m. to 5 p.m. CT Monday through Friday or online at www.exmark.com and click on Service & Support and then on Safety Resources at the bottom of the page for more information

[Report an Incident Involving this Product](#)

The U.S. Consumer Product Safety Commission is charged with protecting the public from unreasonable risks of injury or death associated with the use of thousands of types of consumer products under the agency's jurisdiction. Deaths, injuries, and property damage from consumer product incidents cost the nation more than \$1 trillion annually. CPSC is committed to protecting consumers and families from products that pose a fire, electrical, chemical or mechanical hazard. CPSC's work to help ensure the safety of consumer products - such as toys, cribs, power tools, cigarette lighters and household chemicals -- contributed to a decline in the rate of deaths and injuries associated with consumer products over the past 40 years.

Federal law bars any person from selling products subject to a publicly-announced voluntary recall by a manufacturer or a mandatory recall ordered by the Commission.

Recall Details

In conjunction with



Units

About 6,900 in the United States and 330 in Canada

Description

This recall involves 2013 Exmark Commercial 30” Walk-Behind Mowers, model ECKA30 and serial numbers ranging from 313605897 to 313660824. The phrases “Commercial 30” and “Exmark” are printed on the front of the black and red mower. “Exmark” is also printed on the side of the mower. The model and serial numbers are located on a decal affixed to the engine base above the left rear tire.

Incidents/Injuries

None

Remedy

Consumers should immediately stop using the recalled mowers and contact Exmark for a free repair.

Sold at

Exmark dealers nationwide from November 2012 through October 2013 for about \$1,800.

Distributor

Exmark Manufacturing Company, Inc., from Beatrice, Neb.

Manufactured in

Mexico

To report a dangerous product or a product-related injury go online to www.SaferProducts.gov or call CPSC's Hotline at (800) 638-2772 or teletypewriter at (301) 595-7054 for the hearing impaired. Consumers can obtain news release and recall information at www.cpsc.gov, on Twitter [@OnSafety](https://twitter.com/OnSafety) or by subscribing to CPSC's [free e-mail newsletters](#).



Recalled Exmark commercial
walk-behind mower